1426-1446 East Baltimore Street (Commerical Buildings)
1444 East Baltimore Street
Baltimore (Independent City)
Maryland

HABS No. MD-904-I

HABS MD, 4-BALT, 153 I -

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

MD, 4-BALT, 153I-

ARCHITECTURAL DATA FORM

ATE	COUNTY	COUNTY		TOWN OR VICINITY	
Maryland			Raltimo	Baltimore	
				HABS NO.	
1426-46East Baltimore Street (Commercial Buildings) MD-904-1					
SECONDARY OR COMMON NAMES OF STRUCTURE					
1444 East Baltimore Street					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
1444 East Baltimore Street					
DATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCL	ARCHITECT(S) (INCLUDE SOURCE)		
	. 1860 (1869 Sachsey map)		Unknown		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)					
Original use presumed to be a residence with a shop below based on detaining of					
storefront and stair.					
STYLE (IF APPROPRIATE) Victorian					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
Brick bearing walls: wood joists and floors: built-up roof: wood doors windows					
APE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)					
Overall 18' x 56' Front 18'x 30' Rear 14' x 26' (see sketch plan)					
EXTERIOR FEATURES OF NOTE					
Metal Cornice; red brick common bond, flat-arched window openings					
The control of the street common sond, the carened william openings					
INTERIOR FEATURES OF NOTE (DESCR		•			
Bullseye window and door trim, board and bead wainscoting in stairs and utility rooms, wood floors. A detail of note are the transoms above all doors between public rooms					
(living and dining) and between major rooms and the corridor.					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES					
·					
Back porch addition Circa 1906 on Third floor. Storefront alterations					
PRESENT CONDITION AND USE					
Vacant-rear of building suffering substantial damage from brick robbers.					
OTHER INFORMATION AS APPROPRIATE For photographs, see HABS No. MD-904.					
Building is to be renovated for cooperative housing for artists.					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
1869 Sachsey Map, 1887 Bromley Map, Sanborn Maps 1902, 1911, 1927, 1932					
COMPILER, AFFILIATION				DATE	
Peter C. Doo. AIA Walter Sc	hamu & Associ	ates	Ī	23 Sept. 1985	

